

# Oil Field Environmental Incident Summary

**Incident:** 20150428122422      **Date/Time of Notice:** 04/28/2015 12:24

**Responsible Party:** Oasis Petroleum

**Well Operator:** OASIS PETROLEUM NORTH AMERICA LLC

**Well Name:** OASIS 5202-7-6 CTB (KELTER)

**Field Name:** EIGHTMILE

**Well File #:**

**Date Incident:** 4/26/2015      **Time Incident:** 18:30      **Facility ID Number:** 220626-01

**County:** MCKENZIE      **Twp:** 152      **Rng:** 102      **Sec:** 7      **Qtr:**

**Location Description:**

**Submitted By:** Lance Bethke

**Received By:**

**Contact Person:** Lance Bethke  
1001 FANNIN STE 1500  
HOUSTON, TX 77002

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 1 Mile

**Distance Nearest Water Well:** 2 Mile

**Type of Incident:** Treater Leak

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** Unknown

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	20	Barrels	20	Barrels	20	barrels

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 3/23/2016

**Clean Up Concluded:** 5/1/2015

**Risk Evaluation:**

No immediate risks

**Areal Extent:**

**Potential Environmental Impacts:**

No environmental impacts

**Action Taken or Planned:**

Drained remaining fluid in to production tank, and will replace all gaskets on treaters

**Wastes Disposal Location:** The oil will be put in oil tank and contaminated soil will be hauled to IHD disposal

**Agencies Involved:**

**Updates**

**Date:** 4/28/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to tank overflow, remained on location within the diking according to the report. NDIC retains oversight.